




"Y" connector



To reset the Plus One:

1. Plug the two pin female *optimize/calibration* connector into the harness in the dash.
2. Plug the *optimize* plug into the *optimize* connector and the *calibrate* plug into the *calibrate* connector.
3. Turn on the ignition and observe the status light.
4. When the status light goes out, turn off the ignition and remove the "Y" connector.
5. Attempt to start the engine, if engine will not start reset was successful.
6. Perform the optimization and calibration procedure.

NOTE: "Y" connector part number is 989964-03